

### PULL OUT TORQUE CURVE OF 42HS79-8004S

Microstep :1600  
Current :8.2A

● 220VAC



